Iridium Keyboard Synthesizer – list of fixed bug & new features

_____

2.8.4 – 2022 – march

Release contains new panel firmware 0.4.
Please update after main firmware update.

Bug Fixes & Improvements:

– Time resolution of pitch bend events sent to external MIDI increased.
– Pitch Bend reacts more tigh to incoming events.
– Touch screen plays notes in Note, Scale & Chord screens.
– Info panel shown at boot when wheel calibration is needed.

2.8.3 – 2021

– Factory Headphone Test improved

It has a new feature on the Master->Levels page to switch from poly AT to traditional mono AT. This setting will be stored in the patch and therefore can be individually set per patch.

Otherwise it contains a few bug fixes:

- USB Host port: Improving MIDI output messaging
- Update procedure: Accepting update files from subdirectories

2.8.2 – 2021

New Features:

– Mono AT option
It has a new feature on the Master–>Levels page to switch from poly AT to traditional mono AT. This setting will be stored in the patch and therefore can be individually set per patch.

Bug Fixes:

– Subfolder Install fix
– USB fixes
FS#1637: Changed split values on init patch for load and power up to the same

2.8.1 – 2021

New Features:

– Attack/Release Parameters for Aftertouch (on Levels screen)

FS#1639 – XY pad send midi CCs

Bug Fixes:

FS#1630 — seq|arp button changes param seq to arp
FS#1653 — Arpeggiator screen leaves artifacts

2.8.0 — 2021 — december

New Features:

— New After Touch calibration screen

Bug Fixes:

— Improving master limiter
— Sample Import / Export fix for loading samples

FS#1431 — Folder disappears after renaming
FS#1612 — Stuck notes when switching octaves
FS#1611 — Mod button wording